







Drill hole 28mm Diameter

Remove factory Sensors and fit Grommets supplied







sale T bar

Ensure Sensors are refitted in the same orientation as originally fitted



The nearside sensor housing will need modification to allow the sensor cable plug to exit on the opposite side to original.



This is achieved by cutting a new slot on the opposite side of the housing as seen in the picture

If you need advise please telephone 01344 624855